



HANDOVER PROOF RECEIPT



SCUFF SEAL · LOCKED

MANIFEST DIGEST C5F53487C7EC · SHA-256 OVER 6 ITEMS · GENERATED 28 SEP 2026 AT 09:44

ITEM	COUNTERPARTY / REF	TYPE
Airport rental car	Booking ref RSC-4821	Handover
CAPTURED	CONTENTS	PHOTO SOURCE
28 Sep 2026 at 09:41	6 photos · 3 sections	6 captured in Rentscuff

RECEIPT QUALITY

100%**STRONG**

EVIDENCE INTEGRITY

- ✓ **Locked original.** Original capture references kept with the receipt.
- ✓ **Metadata.** Timestamp, section, item label, and condition tag included.
- ✓ **Photo digest.** 6 photo item digests recorded.
- ✓ **Receipt digest.** Short digest c5f53487c7ec links this receipt summary to its manifest.

Every photo is fingerprinted with SHA-256 as it is saved. Those fingerprints — with each section, item, condition, note and capture time — fold into the manifest digest shown here. Change any of them afterwards and the digest no longer matches.

01 · SUMMARY

Receipt type, item, dates, counts, quality, and Scuff Seal digest.

02 · NOTED FINDINGS

6 captured items organized for fast review.

03 · EVIDENCE APPENDIX

3 sections with media references, notes, and timestamps.

#	SECTION · ITEM	CONDITION	NOTE	CAPTURED
01	 Exterior · Front and passenger side	GOOD	Wide overview before leaving the collection bay.	09:41:00
02	 Exterior · Rear quarter	SCRATCHED	Light scratch above the rear wheel, present at handover.	09:42:00
03	 Exterior · Driver handover	GOOD	Vehicle and keys received at the collection point.	09:43:00
04	 Interior · Dashboard and mileage	GOOD	Dashboard and odometer recorded at collection.	09:44:00




#		SECTION · ITEM	CONDITION	NOTE	CAPTURED
05		Interior · Seats and cabin	CLEAN	Cabin overview before the journey.	09:45:00
06		Handover · Keys and booking reference	GOOD	Keys and booking reference recorded together at collection.	09:46:00



PLATE 1 OF 6

EXTERIOR · FRONT AND PASSENGER SIDE · CAPTURED 28 SEP
2026 AT 09:41:00



EXTERIOR · FRONT AND PASSENGER SIDE

GOOD

Wide overview before leaving the collection bay.

sha256 3fbf3543629a1bdbb378b34ed1417a74f8da2e453e5a50308b8e3d8e0907560c · 553,920 bytes · photo · captured in Rentscuff



PLATE 2 OF 6

EXTERIOR · REAR QUARTER · CAPTURED 28 SEP 2026 AT
09:42:00

1 SCUFF CIRCLED



EXTERIOR · REAR QUARTER

SCRATCHED


Light scratch above the rear wheel, present at handover.

sha256 4aae1aef1d0a0d54255c3114010fc6a1c848923c23f64895fff29dcbf8c31c35 · 532,659 bytes · photo · captured in Rentscuff



PLATE 3 OF 6

EXTERIOR · DRIVER HANDOVER · CAPTURED 28 SEP 2026 AT
09:43:00



EXTERIOR · DRIVER HANDOVER GOOD

Vehicle and keys received at the collection point.

sha256 65db7386a06ddfb978ff103f99e233647b3f2ae08fb9b91cfb91fb6b4ebb399d · 284,603 bytes · photo · captured in Rentscuff



PLATE 4 OF 6

INTERIOR · DASHBOARD AND MILEAGE · CAPTURED 28 SEP 2026
AT 09:44:00



INTERIOR · DASHBOARD AND MILEAGE GOOD

Dashboard and odometer recorded at collection.

sha256 a5932c7272684027f3884b4de7a2d86eea876faca2cab5e1340fb5bff2162667 · 539,156 bytes · photo · captured in Rentscuff



PLATE 5 OF 6

INTERIOR · SEATS AND CABIN · CAPTURED 28 SEP 2026 AT
09:45:00



INTERIOR · SEATS AND CABIN

CLEAN


Cabin overview before the journey.

sha256 9e44f51d3042a9f612b20b3a3347546780cdb883124c48d5bbf57639af5fe9ff · 474,209 bytes · photo · captured in Rentscuff



PLATE 6 OF 6

HANDOVER · KEYS AND BOOKING REFERENCE · CAPTURED 28 SEP
2026 AT 09:46:00



HANDOVER · KEYS AND BOOKING REFERENCE

GOOD

Keys and booking reference recorded together at collection.

sha256 9e339b38ca3f931c4b64667a0833a64faf607ab2510d290ab0d7ac4644f3db81 · 409,981 bytes · photo · captured in Rentscuff